



TO: All HRL Employees,
Vendors and Tenants

DATE: July 18, 2017

SUBJECT: ASBESTOS-CONTAINING
CONSTRUCTION MATERIALS
(ACCM) NOTIFICATION

Julie Jackson
FROM: J. Jackson
ORG: 30-44-00

The California Health and Safety Code (Asbestos Notification, Section 25915 et seq.) requires HRL to notify, inform and annually update its employees on the presence and location of asbestos-containing construction materials (ACCM) in its facility.

Our buildings, constructed prior to 1979, contain some quantity of ACCM. However, all ACCM is presently covered or sealed to prevent it from being released into the ambient air. Based on a survey in August 2000 of all the HRL buildings, you are advised that the ACCM has been identified, is in good condition, and remains in the following areas:

Location	ACCM
Building 250	Floor Tiles: 9"x9" (yellow, tan) and 12"x12" (white, olive, brown); Joint compound; Duct mastic, pipe elbows above ceiling, vinyl floor tile mastic, roofing and duct mastic on roof, wood tile adhesive/mastic
Building 251	Vinyl floor tile mastic
Building 254	Transite panels in lab hoods (these panels have Asbestos Warning labels affixed)
Building 257	Transite table tops, vinyl floor tile and mastic, duct and roofing mastic on roof
Building 258	Roofing mastic
Building 761	Roofing and duct mastic located on roof

Exposure to asbestos fibers is known to cause cancer and other lung diseases. Accordingly, you are directed not to disturb these materials in any manner. Any disturbance or removal of ACCM must only be done with the approval and supervision of the HRL Facilities and Environmental Health & Safety (EH&S) staff. This will assure the safety of all employees in the affected area. If you observe any deterioration or disturbance of ACCM, notify a member of the EH&S staff immediately.

Our knowledge of the existence of ACCM at this site is based upon surveys conducted at HRL. The results of the surveys are available for your review in the EH&S office in a paper copy or on the EH&S SharePoint Site at <https://myoffice.hrl.com/enterprise/ehs/layouts/15/start.aspx#/SitePages/Home.aspx>. If you should have any questions or concerns, please call EH&S at Ext. 4747.